

**Custodial Services Audit Results - September 2016**  
**Administrative Environment**

<b>Summary</b>	<b>Restroom</b>	<b>Entry</b>	<b>Corridor</b>	<b>Lounge</b>	<b>Office</b>	<b>Utility</b>	<b>Core Avg</b>
300 S Craig	86.19%	82.31%	81.81%	81.44%	81.31%	81.31%	81.64%
319 S Craig	84.50%	82.00%	81.75%	82.38%	82.19%	81.69%	82.00%
6555 Penn	84.69%	81.75%	83.06%	81.63%	81.06%	81.31%	81.76%
Alumni	85.13%	82.44%	82.31%	81.88%	82.19%	81.94%	82.15%
Bramer	84.13%	81.69%	81.50%	81.38%	81.25%	81.13%	81.39%
Cyert	84.13%	81.35%	81.50%	81.19%	81.25%	81.19%	81.30%
FMS	84.13%	81.38%	81.13%	81.06%	81.25%	81.13%	81.19%
GATF	84.94%	83.00%	82.22%	82.50%	82.81%	82.50%	82.61%
INI	85.69%	83.44%	84.13%	83.75%	82.25%	82.31%	83.18%
UTDC	84.31%	82.00%	82.44%	82.50%	81.69%	82.38%	82.20%
Whitfield	85.00%	82.75%	81.63%	83.00%	81.63%	81.56%	82.11%
Warner	85.31%	83.44%	81.69%	82.50%	82.50%	81.56%	82.34%
<b>Average</b>	<b>84.85%</b>	<b>82.30%</b>	<b>82.10%</b>	<b>82.10%</b>	<b>81.78%</b>	<b>81.67%</b>	<b>81.99%</b>
<i>Passing</i>	<i>84%</i>	<i>83%</i>	<i>83%</i>	<i>83%</i>	<i>83%</i>	<i>83%</i>	<i>81%</i>

<b>300 S Craig</b>	<b>Restroom</b>	<b>Entry</b>	<b>Corridor</b>	<b>Lounge</b>	<b>Office</b>	<b>Utility</b>	<b>Core Avg</b>
Ceiling	85.50%	82.50%	82.50%	82.50%	81.25%	82.50%	82.25%
Walls	84.75%	81.25%	81.50%	81.25%	81.25%	80.75%	81.20%
Floor	87.50%	83.00%	81.25%	80.75%	81.25%	80.75%	81.40%
Fixtures	87.00%	82.50%	82.00%	81.25%	81.50%	81.25%	81.70%
<b>Average</b>	<b>86.19%</b>	<b>82.31%</b>	<b>81.81%</b>	<b>81.44%</b>	<b>81.31%</b>	<b>81.31%</b>	<b>81.64%</b>
<i>Passing</i>	<i>84%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>

<b>319 S Craig</b>	<b>Restroom</b>	<b>Entry</b>	<b>Corridor</b>	<b>Lounge</b>	<b>Office</b>	<b>Utility</b>	<b>Core Avg</b>
Ceiling	85.00%	82.50%	81.50%	82.50%	83.00%	82.50%	82.40%
Walls	84.50%	83.00%	81.25%	82.50%	81.25%	81.25%	81.85%
Floor	84.00%	81.25%	82.25%	82.00%	82.00%	81.25%	81.75%
Fixtures	84.50%	81.25%	82.00%	82.50%	82.50%	81.75%	82.00%
<b>Average</b>	<b>84.50%</b>	<b>82.00%</b>	<b>81.75%</b>	<b>82.38%</b>	<b>82.19%</b>	<b>81.69%</b>	<b>82.00%</b>
<i>Passing</i>	<i>84%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>

<b>6555 Penn</b>	<b>Restroom</b>	<b>Entry</b>	<b>Corridor</b>	<b>Lounge</b>	<b>Office</b>	<b>Utility</b>	<b>Core Avg</b>
Ceiling	84.75%	82.50%	85.00%	82.50%	82.50%	82.50%	83.00%
Walls	84.50%	81.25%	83.00%	81.25%	80.75%	80.75%	81.40%
Floor	84.50%	81.50%	83.00%	81.25%	80.00%	80.75%	81.30%
Fixtures	85.00%	81.75%	81.25%	81.50%	81.00%	81.25%	81.35%
<b>Average</b>	<b>84.69%</b>	<b>81.75%</b>	<b>83.06%</b>	<b>81.63%</b>	<b>81.06%</b>	<b>81.31%</b>	<b>81.76%</b>
<i>Passing</i>	<i>84%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>	<i>81%</i>

<b>Alumni</b>	<b>Restroom</b>	<b>Entry</b>	<b>Corridor</b>	<b>Lounge</b>	<b>Office</b>	<b>Utility</b>	<b>Core Avg</b>
Ceiling	85.50%	82.50%	83.00%	82.50%	83.00%	83.00%	82.80%
Walls	85.00%	82.50%	82.50%	81.50%	82.50%	82.50%	82.30%
Floor	84.50%	82.25%	81.25%	81.50%	82.00%	81.25%	81.65%
Fixtures	85.50%	82.50%	82.50%	82.00%	81.25%	81.00%	81.85%
<b>Average</b>	<b>85.13%</b>	<b>82.44%</b>	<b>82.31%</b>	<b>81.88%</b>	<b>82.19%</b>	<b>81.94%</b>	<b>82.15%</b>

**Custodial Services Audit Results - September 2016**  
**Administrative Environment**

Passing 84% | 81% 81% 81% 81% 81% | 81%

<b>Bramer</b>	Restroom	Entry	Corridor	Lounge	Office	Utility	Core Avg
Ceiling	84.50%	81.50%	82.00%	82.00%	82.25%	81.25%	81.80%
Walls	84.00%	81.50%	81.50%	81.25%	81.00%	81.25%	81.30%
Floor	83.75%	82.00%	81.25%	81.25%	80.50%	81.25%	81.25%
Fixtures	84.25%	81.75%	81.25%	81.00%	81.25%	80.75%	81.20%
Average	84.13%	81.69%	81.50%	81.38%	81.25%	81.13%	81.39%
Passing	84%	81%	81%	81%	81%	81%	81%

<b>Cyert</b>	Restroom	Entry	Corridor	Lounge	Office	Utility	Core Avg
Ceiling	84.50%	81.25%	82.00%	81.50%	81.50%	81.50%	81.55%
Walls	84.25%	81.40%	81.50%	81.25%	81.25%	81.25%	81.33%
Floor	83.75%	81.25%	81.25%	81.00%	81.00%	81.00%	81.10%
Fixtures	84.00%	81.50%	81.25%	81.00%	81.25%	81.00%	81.20%
Average	84.13%	81.35%	81.50%	81.19%	81.25%	81.19%	81.30%
Passing	84%	81%	81%	81%	81%	81%	81%

<b>FMS</b>	Restroom	Entry	Corridor	Lounge	Office	Utility	Core Avg
Ceiling	84.25%	81.50%	81.75%	81.50%	81.75%	81.50%	81.60%
Walls	84.00%	81.25%	81.00%	80.75%	81.00%	81.00%	81.00%
Floor	83.75%	81.25%	80.75%	80.75%	81.00%	80.75%	80.90%
Fixtures	84.50%	81.50%	81.00%	81.25%	81.25%	81.25%	81.25%
Average	84.13%	81.38%	81.13%	81.06%	81.25%	81.13%	81.19%
Passing	84%	81%	81%	81%	81%	81%	81%

<b>GATF</b>	Restroom	Entry	Corridor	Lounge	Office	Utility	Core Avg
Ceiling	85.25%	83.00%	83.13%	83.00%	83.00%	83.50%	83.13%
Walls	84.75%	82.50%	81.25%	83.00%	83.00%	82.50%	82.45%
Floor	84.75%	83.00%	82.00%	82.00%	82.50%	82.00%	82.30%
Fixtures	85.00%	83.50%	82.50%	82.00%	82.75%	82.00%	82.55%
Average	84.94%	83.00%	82.22%	82.50%	82.81%	82.50%	82.61%
Passing	84%	81%	81%	81%	81%	81%	81%

<b>INI</b>	Restroom	Entry	Corridor	Lounge	Office	Utility	Core Avg
Ceiling	86.00%	83.00%	85.50%	85.00%	83.00%	83.00%	83.90%
Walls	85.50%	82.50%	84.00%	83.00%	82.50%	82.00%	82.80%
Floor	85.00%	85.00%	84.50%	84.50%	81.50%	82.00%	83.50%
Fixtures	86.25%	83.25%	82.50%	82.50%	82.00%	82.25%	82.50%
Average	85.69%	83.44%	84.13%	83.75%	82.25%	82.31%	83.18%
Passing	84%	81%	81%	81%	81%	81%	81%

<b>UTDC</b>	Restroom	Entry	Corridor	Lounge	Office	Utility	Core Avg
Ceiling	84.50%	82.50%	83.00%	83.50%	82.00%	83.00%	82.80%
Walls	84.00%	82.00%	82.50%	82.50%	82.00%	82.50%	82.30%
Floor	84.25%	81.50%	82.00%	82.00%	81.25%	82.00%	81.75%

