

## Custodial Services Audit Results - January 2016

### Academic Environment

Summary	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Baker Porter	84.19%	81.03%	83.06%	83.13%	83.06%	81.38%	82.66%
CFA	84.13%	81.03%	83.13%	83.25%	83.19%	83.03%	83.15%
Doherty	84.06%	81.09%	82.97%	83.03%	83.09%	83.09%	83.05%
Gates	84.13%	81.44%	83.09%	83.19%	84.13%	83.25%	83.41%
Hamburg	84.06%	81.03%	83.13%	83.19%	83.25%	83.03%	83.15%
Hamerschlag	84.00%	81.00%	83.06%	83.03%	82.88%	83.19%	83.04%
Hunt	83.94%	81.00%	82.69%	82.97%	83.00%	82.88%	82.88%
Mellon	83.91%	81.13%	84.09%	84.06%	83.97%	83.97%	84.02%
MMCH	84.09%	81.16%	83.03%	83.06%	83.06%	83.00%	83.04%
Newell Simon	84.06%	81.06%	83.25%	83.44%	83.13%	83.25%	83.27%
Purnell	84.00%	81.06%	83.03%	83.13%	83.00%	83.16%	83.08%
PTC	84.19%	81.13%	83.38%	83.13%	83.13%	83.19%	83.20%
Roberts	84.31%	81.13%	84.13%	82.69%	83.06%	83.03%	83.23%
Scaife	84.09%	81.09%	83.13%	83.09%	83.09%	83.13%	83.11%
SEI	84.03%	81.13%	83.13%	83.19%	83.38%	83.19%	83.22%
Smith	85.16%	81.06%	83.06%	83.00%	83.06%	83.06%	83.05%
Tepper	84.13%	81.03%	83.06%	83.31%	83.13%	83.13%	83.16%
Wean	86.67%	81.13%	83.25%	83.13%	83.19%	83.19%	83.19%
Average	84.29%	81.10%	83.20%	83.17%	83.21%	83.06%	83.16%
Passing	84%	81%					83%

Baker Porter	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.00%	83.00%	83.25%	83.25%	80.75%	82.56%
Walls	84.25%	81.13%	83.00%	83.00%	83.00%	80.75%	82.44%
Floor	84.00%	81.00%	83.00%	83.00%	82.88%	80.63%	82.38%
Fixtures	84.25%	81.00%	83.25%	83.25%	83.13%	83.38%	83.25%
Average	84.19%	81.03%	83.06%	83.13%	83.06%	81.38%	82.66%
Passing	84%	81%					83%

CFA	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.00%	83.25%	83.50%	83.25%	83.00%	83.25%
Walls	84.25%	81.13%	83.00%	83.25%	83.25%	83.00%	83.13%
Floor	84.25%	81.00%	83.00%	83.00%	83.00%	83.00%	83.00%
Fixtures	84.00%	81.00%	83.25%	83.25%	83.25%	83.13%	83.22%
Average	84.13%	81.03%	83.13%	83.25%	83.19%	83.03%	83.15%
Passing	84%	81%					83%

Doherty	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.25%	83.00%	83.25%	83.25%	83.25%	83.19%
Walls	84.00%	81.00%	82.75%	82.75%	83.00%	82.88%	82.84%
Floor	84.25%	81.00%	82.75%	83.00%	82.88%	83.00%	82.91%
Fixtures	84.00%	81.13%	83.38%	83.13%	83.25%	83.25%	83.25%
Average	84.06%	81.09%	82.97%	83.03%	83.09%	83.09%	83.05%
Passing	84%	81%					83%

<b>Gates</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.50%	83.25%	83.00%	84.00%	83.25%	83.38%
Walls	84.25%	81.50%	82.75%	83.00%	84.00%	83.00%	83.19%
Floor	84.00%	81.25%	83.13%	83.25%	84.25%	83.25%	83.47%
Fixtures	84.00%	81.50%	83.25%	83.50%	84.25%	83.50%	83.63%
Average	84.13%	81.44%	83.09%	83.19%	84.13%	83.25%	83.41%
Passing	84%	81%					83%

<b>Hamburg</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.38%	81.00%	83.25%	83.25%	83.50%	83.00%	83.25%
Walls	83.75%	81.00%	82.88%	83.00%	83.25%	83.00%	83.03%
Floor	84.13%	81.00%	83.13%	83.25%	83.25%	83.00%	83.16%
Fixtures	84.00%	81.13%	83.25%	83.25%	83.00%	83.13%	83.16%
Average	84.06%	81.03%	83.13%	83.19%	83.25%	83.03%	83.15%
Passing	84%	81%					83%

<b>Hamerschlag</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.00%	83.00%	83.00%	83.00%	83.25%	83.06%
Walls	83.75%	80.75%	82.88%	83.00%	83.00%	83.25%	83.03%
Floor	84.00%	81.13%	83.25%	83.00%	82.75%	83.00%	83.00%
Fixtures	84.25%	81.13%	83.13%	83.13%	82.75%	83.25%	83.06%
Average	84.00%	81.00%	83.06%	83.03%	82.88%	83.19%	83.04%
Passing	84%	81%					83%

<b>Hunt</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.00%	83.00%	83.00%	83.00%	83.00%	83.00%
Walls	83.75%	80.88%	82.75%	82.88%	83.25%	82.75%	82.91%
Floor	83.75%	81.00%	82.50%	83.00%	82.75%	83.00%	82.81%
Fixtures	84.25%	81.13%	82.50%	83.00%	83.00%	82.75%	82.81%
Average	83.94%	81.00%	82.69%	82.97%	83.00%	82.88%	82.88%
Passing	84%	81%					83%

<b>Mellon</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.25%	84.00%	84.13%	84.00%	84.00%	84.03%
Walls	83.50%	81.13%	84.00%	84.00%	83.75%	84.00%	83.94%
Floor	83.75%	81.00%	84.13%	84.00%	84.00%	84.00%	84.03%
Fixtures	84.38%	81.13%	84.25%	84.13%	84.13%	83.88%	84.09%
Average	83.91%	81.13%	84.09%	84.06%	83.97%	83.97%	84.02%
Passing	84%	81%					83%

<b>MMCH</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.25%	83.25%	83.25%	83.25%	83.50%	83.31%
Walls	84.00%	81.38%	82.88%	82.88%	82.88%	83.00%	82.91%
Floor	84.13%	80.88%	83.13%	83.13%	83.00%	82.50%	82.94%
Fixtures	84.00%	81.13%	82.88%	83.00%	83.13%	83.00%	83.00%
Average	84.09%	81.16%	83.03%	83.06%	83.06%	83.00%	83.04%
Passing	84%	81%					83%

<b>Newell Simon</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.00%	83.25%	83.25%	83.25%	83.50%	83.31%
Walls	84.25%	81.00%	83.25%	83.75%	83.25%	83.25%	83.38%
Floor	83.75%	81.25%	83.25%	83.25%	83.00%	83.25%	83.19%

Fixtures	84.00%	81.00%	83.25%	83.50%	83.00%	83.00%	83.19%
Average	84.06%	81.06%	83.25%	83.44%	83.13%	83.25%	83.27%
Passing	84%	81%					83%

<b>Purnell</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.25%	83.00%	83.00%	83.25%	83.25%	83.13%
Walls	84.00%	80.75%	83.25%	83.25%	83.00%	83.25%	83.19%
Floor	84.25%	81.00%	82.75%	83.25%	82.75%	83.00%	82.94%
Fixtures	83.75%	81.25%	83.13%	83.00%	83.00%	83.13%	83.06%
Average	84.00%	81.06%	83.03%	83.13%	83.00%	83.16%	83.08%
Passing	84%	81%					83%

<b>PTC</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.50%	83.25%	83.25%	83.25%	83.50%	83.31%
Walls	84.00%	81.25%	83.00%	83.25%	83.00%	83.25%	83.13%
Floor	84.25%	81.00%	83.25%	83.00%	83.25%	83.00%	83.13%
Fixtures	84.25%	80.75%	84.00%	83.00%	83.00%	83.00%	83.25%
Average	84.19%	81.13%	83.38%	83.13%	83.13%	83.19%	83.20%
Passing	84%	81%					83%

<b>Roberts</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.25%	84.50%	83.25%	83.25%	83.00%	83.50%
Walls	84.25%	81.00%	83.50%	83.25%	83.00%	83.00%	83.19%
Floor	84.25%	81.25%	84.25%	83.00%	83.00%	83.13%	83.34%
Fixtures	84.50%	81.00%	84.25%	81.25%	83.00%	83.00%	82.88%
Average	84.31%	81.13%	84.13%	82.69%	83.06%	83.03%	83.23%
Passing	84%	81%					83%

<b>Scaife</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.25%	83.00%	83.25%	83.25%	83.25%	83.19%
Walls	84.25%	81.00%	83.25%	83.25%	83.00%	83.00%	83.13%
Floor	84.00%	81.13%	83.25%	82.88%	83.00%	83.00%	83.03%
Fixtures	83.88%	81.00%	83.00%	83.00%	83.13%	83.25%	83.09%
Average	84.09%	81.09%	83.13%	83.09%	83.09%	83.13%	83.11%
Passing	84%	81%					83%

<b>SEI</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.25%	83.00%	83.25%	83.25%	83.25%	83.19%
Walls	83.88%	81.00%	83.00%	83.25%	83.25%	83.25%	83.19%
Floor	84.25%	81.00%	83.25%	83.00%	83.50%	83.25%	83.25%
Fixtures	84.00%	81.25%	83.25%	83.25%	83.50%	83.00%	83.25%
Average	84.03%	81.13%	83.13%	83.19%	83.38%	83.19%	83.22%
Passing	84%	81%					83%

<b>Smith</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.00%	81.00%	83.00%	83.25%	83.25%	83.25%	83.19%
Walls	83.75%	81.00%	83.00%	82.75%	83.25%	83.00%	83.00%
Floor	84.00%	81.00%	83.25%	83.00%	82.75%	83.00%	83.00%
Fixtures	88.88%	81.25%	83.00%	83.00%	83.00%	83.00%	83.00%
Average	85.16%	81.06%	83.06%	83.00%	83.06%	83.06%	83.05%
Passing	84%	81%					83%

<b>Tepper</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	84.25%	81.00%	83.25%	83.50%	83.25%	83.25%	83.31%
Walls	84.25%	81.00%	83.25%	83.25%	83.25%	83.25%	83.25%
Floor	84.00%	81.00%	83.00%	83.25%	83.25%	83.13%	83.16%
Fixtures	84.00%	81.13%	82.75%	83.25%	82.75%	82.88%	82.91%
Average	84.13%	81.03%	83.06%	83.31%	83.13%	83.13%	83.16%
Passing	84%	81%					83%

<b>Wean</b>	Restroom	Office	Cooridor	Entry	Classroom	Assembly	Core Avg
Ceiling	83.93%	81.25%	83.25%	83.25%	83.50%	83.25%	83.31%
Walls	84.25%	81.00%	83.00%	83.00%	83.25%	83.00%	83.06%
Floor	89.25%	81.00%	83.25%	83.25%	83.00%	83.25%	83.19%
Fixtures	89.25%	81.25%	83.50%	83.00%	83.00%	83.25%	83.19%
Average	86.67%	81.13%	83.25%	83.13%	83.19%	83.19%	83.19%
Passing	84%	81%					83%